

From: [Wallingford, Jonni B.](#)
To: [Sheldrake, Sean](#); [Zhen, Davis](#); [Young, Hunter](#)
Cc: [Scott Coffey](#); younghs@cdmsmith.com; [Vickstrom, Kyle E.](#)
Subject: Fish Tracking Oversight
Date: Monday, March 18, 2019 1:12:36 PM
Attachments: [IMG_20190318_125311448_HDR.jpg](#)
[IMG_20190318_125329832.jpg](#)
[IMG_20190318_125321491.jpg](#)

Good afternoon,

The Pre-RD group has completed status checks for all receivers upriver of SIL (AR's 18-34). The crew has motored downriver to RM 2 and will work their way back up to SIL, completing checks for the remaining 18 receivers. All receivers checked this morning have reported memory usage of 0-4%, battery life remaining 60-64%, and tilt angles less than 8°.

Jonni

(b) (6)

Arriving at RM 2, establishing communication with AR-A01



RM 2 facing North



Hydrophone in water



Get [Outlook for Android](#)